

Table of Contents

INDEX	2
SUZUKI STARTER IMAGES	2
SUZUKI TRIM MOTOR IMAGES	3
SUZUKI SOLENOIDS & RELAY IMAGES	4
SUZUKI APPLICATION BY YEAR - HP	5



SUZUKI

<p>HIT52</p>		<p>PMDD 12 Volt</p> <p>CCW 9 Tooth</p>	<p>Suits: 20hp - 40hp 2 stroke from 1980 up</p> <p>Hitachi: S108-112, S108-120, S108-94, S108-94C Suzuki: 31100-94400, 31100-94401, 31100-94402, 31100-96310, 31100-96311</p>
<p>HIT87</p>		<p>PMDD 12 Volt</p> <p>CCW 9 Tooth</p>	<p>Suits: DT50, DT65 2 stroke from 1980-1983</p> <p>Hitachi: S114-220, S114-221, E, F, G, H, J Suzuki: 31100-95240, 31100-95242</p>
<p>HIT89</p>		<p>PMDD 12 Volt</p> <p>CCW 9 Tooth</p>	<p>Suits: 50hp – 85hp 2 stroke from 1980 - 1997</p> <p>Hitachi: S114-407, S114-555 Suzuki: 31100-95310, 31100-95312, 31100-95313, 31100-95600, 31100-95601</p>
<p>HIT90</p>		<p>PMDD 12 Volt</p> <p>CCW 9 Tooth</p>	<p>Suits: 115hp – 140hp 2 stroke from 1985 - 2001</p> <p>Hitachi: S114-437, S114-673 Suzuki: 31100-94600, 31100-94601, 31100-94610</p>
<p>HIT91</p>		<p>PMDD 12 Volt</p> <p>CCW 8 Tooth</p>	<p>Suits: 90hp – 100hp, 150hp - 225hp 2 stroke from 1986 - 2003</p> <p>Hitachi: S114-551, S114-551A, S114-674 Suzuki: 31100-87D00, 31100-87D10, 31100-92E00</p>
<p>HIT162</p>		<p>DD 12 Volt</p> <p>CCW 9 Tooth</p>	<p>Suits: DT55 -DT65 2 stroke from 1985 - 1997</p> <p>Hitachi: S114-436 Suzuki: 31100-94702</p>
<p>HIT163</p>		<p>DD 12 Volt</p> <p>CCW 8 Tooth</p>	<p>Suits DF25 4 stroke from 2000 - 2006 DF30 4 stroke from 2000 - 2007</p> <p>Hitachi: S108-122A Suzuki: 31100-89J01</p>
<p>HIT165</p>		<p>PMGR 12 Volt</p> <p>CW 9 Tooth</p>	<p>Suits DF90 4 stroke from 2001 - 2008 DF100 - DF140 from 2001 - 2014</p> <p>NOTE: Genuine Hitachi unit also available. See S114-837A below</p> <p>Hitachi: S114-837, S114-837A Suzuki: 31100-90J00, 31100-90J01</p>



SUZUKI

<p>HIT181</p>		<p>PMDD 12 Volt</p> <p>CCW 8 Tooth</p>	<p>Suits: DF40 4 stroke from 1999 - 2000 DF50 4 stroke from 1999 - 2000 DF60 4 stroke from 1998 - 2000 Hitachi: S114-671A Suzuki: 31100-87500, 31100-87J00</p>
<p>HIT186</p>		<p>PMGR 12 Volt</p> <p>CCW 9 Tooth</p>	<p>Suits: DF9.9, DF15, DF20, DF40, DF50 4 stroke from 2005 - 2014 DF25 4 stroke V-Twin from 2006 - 2014 DF60 4 stroke from 2010 - 2014 Hitachi: S114-912A, S114-924A Suzuki: 31100-95J00, 31100-95J01, 31100-94J10, 31100-94J20 31100-94J21, 31100-94J22</p>
<p>HIT188</p>		<p>PMGR 12 Volt</p> <p>CW 9 Tooth</p>	<p>Suits: DF70, DF80, DF90 4 stroke from 2009 - 2014 DF150, DF175 4 stroke from 2006 - 2014 DF200, DF225, DF250 4 stroke from 2004 - 2014 DF300 4 stroke from 2007 - 2014 Hitachi: S114-868B Suzuki: 31100-93J00, 31100-93J02, 31100-96J00, 31100-96J01</p>
<p>S114-837A</p>		<p>PMGR 12 Volt</p> <p>CW 9 Tooth</p>	<p>Suits DF90 4 stroke from 2001 - 2008 DF100 - DF140 from 2001 - 2014 NOTE: This is a genuine Hitachi unit. For aftermarket unit see HIT165 Hitachi: S114-837, S114-837A Suzuki: 31100-90J00, 31100-90J01</p>
<p>TRM45</p>		<p>12 Volt</p> <p>3 wire 3 hole</p>	<p>Suits: 4 cyl and V6 DT 2 stroke models from 1986 - 1990</p> <p>Suzuki: 38100-87D00-01T, 38100-87D00-02H, 38100-87E10-0ED</p>
<p>TRM63</p>		<p>12 Volt</p> <p>2 Wire 3 hole</p>	<p>Suits: DT90 from 91-97, DT100 from 91-00, DT150 from 91 up, DT175 from 91-92, DT200 from 91 up, DT225 from 91 up Note: Internal Hex shaft</p> <p>Suzuki: 38100-87D10-0ED, 38100-87E20-0ED, 38100-92E00-0ED</p>
<p>TRM85</p>		<p>12 Volt</p> <p>2 Wire 4 hole</p>	<p>Suits: DF40 -DF50 4 stroke from 2001 - 2010</p> <p>Suzuki: 38100-87J11, 38100-87J20</p>
<p>TRM95</p>		<p>12 Volt</p> <p>2 Wire 4 hole</p>	<p>Suits: DF60 - DF300 4 stroke from 2001 - 2007</p> <p>Suzuki: 38100-92J02</p>



SUZUKI

TRM96		12 Volt 2 Wire 4 hole	Suits: DF40 -DF50 4 stroke from 1999 - 2000 Note: Internal Hex shaft Suzuki: 38100-87J00-0EP
TRM104		12 Volt 2 Wire 4 hole	Suits: DF150, DF175 from 2006 up DF200, DF225, DF250 from 2004 -2010 DF300 from 2007 - 2010 Suzuki: 38100-93J01, 38100-93J02, 38100-93J03, 38100-93J04, 38100-96J00
TRM105		12 Volt 2 Wire 4 hole	Suits: DF90, DF115, DF140 from 2008 up Suzuki: 38100-92J02, 38100-92J10
TRM107		12 Volt 2 Wire 4 hole	Suits: DF40A, DF50A, DF60A from 2010 up Suzuki: 38100-88L00, 38100-88L11
6023		Starter Solenoid 12 Volt	Suits: DT15-DT40 from 1989 up DT115, DT140 from 86-01 DT150, DT200, DT225 from 98 - 03 Suzuki: 31800-94401
6130		Starter Solenoid 12 Volt	Suits: DF9.9-DF20 from 05 up, DF40-60 from 05 up, DF70 from 09 up, DF90-140 from 01 up, DF150-300 from 04 up NOTE: Designed as universal fit unit. Fits HIT165, HIT186, HIT188 Suzuki: 31220-94J00, 31220-90J00



BACK TO INDEX
 SELECT HERE 



DT50ECL	84	48.7ci - 50HP	31100-95310	HIT89
DT60CL	84-83	48.7ci - 60HP	31100-95310	HIT89
DT75TCL	97-88	73.0ci - 75HP	31100-95601	HIT89
DT75TCL	87-83	73.0ci - 75HP	31100-95312	HIT89
DT85EL	80	73.5ci - 85HP	31100-95313	HIT89
DT85TCL	00-88	73.0ci - 85HP	31100-95601	HIT89
DT85TCL	87-82	73.0ci - 85HP	31100-95312	HIT89
DT85TEL	80	73.5ci - 85HP	31100-95313	HIT89
PU85	96-92	73.0ci - 85HP	31100-95600	HIT89

DT115STCL EFI	01-00	108.2ci - 115HP	31100-94610	HIT90
DT115STCL EFI	99-96	108.2ci - 115HP	31100-94600	HIT90
DT115TCL	96-86	108.2ci - 115HP	31100-94600	HIT90
DT115TCX	97-85	108.2ci - 115HP	31100-94600	HIT90
DT140TCL	97-85	108.2ci - 140HP	31100-94600	HIT90
DT140TCL EFI	01-00	108.2ci - 140HP	31100-94610	HIT90
DT140TCL EFI	99-98	108.2ci - 140HP	31100-94600	HIT90
DT140TCX	96-85	108.2ci - 140HP	31100-94600	HIT90
DT140TCX EFI	01-00	108.2ci - 140HP	31100-94610	HIT90
DT140TCX EFI	99-97	108.2ci - 140HP	31100-94600	HIT90
PU140	96-92	108.2ci - 140HP	31100-94600	HIT90



DT90TCL	97-89	86.6ci - 90HP	31100-87D10	HIT91
DT90TCX	90-89	86.6ci - 90HP	31100-87D10	HIT91
DT100SF	90-89	86.6ci - 100HP	31100-87D10	HIT91
DT100TCL	00	86.6ci - 100HP	31100-92E00	HIT91
DT100TCL	99-89	86.6ci - 100HP	31100-87D10	HIT91
DT100TCX	90-89	86.6ci - 100HP	31100-87D10	HIT91
DT150SS	91-86	164.3ci - 150HP	31100-87D10	HIT91
DT150SSN Super S92		164.3ci - 150HP	31100-87D10	HIT91
DT150STCL EFI	03-00	164.3ci - 150HP	31100-92E00	HIT91
DT150STCL EFI	99-94	164.3ci - 150HP	31100-87D10	HIT91

DT150STCL EFI	93	164.3ci - 150HP	31100-87D10	HIT91
DT150TCL	94-86	164.3ci - 150HP	31100-87D10	HIT91
DT150TCX	94-86	164.3ci - 150HP	31100-87D10	HIT91
DT150TCX EFI	03-00	164.3ci - 150HP	31100-92E00	HIT91
DT150TCX EFI	99-95	164.3ci - 150HP	31100-87D10	HIT91
DT150TCXG	94-90	164.3ci - 150HP	31100-87D10	HIT91
DT150TCXG EFI	03-00	164.3ci - 150HP	31100-92E00	HIT91
DT150TCXG EFI	99-95	164.3ci - 150HP	31100-87D10	HIT91
DT175TCL	92-87	164.3ci - 175HP	31100-87D10	HIT91
DT175TCX	92-87	164.3ci - 175HP	31100-87D10	HIT91
DT200AEL	87	164.3ci - 200HP	31100-87D10	HIT91
DT200AEX	87	164.3ci - 200HP	31100-87D10	HIT91
DT200TCL	93-86	164.3ci - 200HP	31100-87D10	HIT91
DT200TCL EFI	00	164.3ci - 200HP	31100-92E00	HIT91
DT200TCL EFI	99-94	164.3ci - 200HP	31100-87D10	HIT91
DT200TCX	93-86	164.3ci - 200HP	31100-87D10	HIT91
DT200TCX EFI	00	164.3ci - 200HP	31100-92E00	HIT91
DT200TCX EFI	99-94	164.3ci - 200HP	31100-87D10	HIT91
DT200TCXG	93-90	164.3ci - 200HP	31100-87D10	HIT91
DT200TCXG EFI	00	164.3ci - 200HP	31100-92E00	HIT91
DT200TCXG EFI	99-94	164.3ci - 200HP	31100-87D10	HIT91
DT200VL Exante	92-88	164.3ci - 200HP	31100-87D10	HIT91
DT200VX Exante	92-88	164.3ci - 200HP	31100-87D10	HIT91
DT200VXG	91-90	164.3ci - 200HP	31100-87D10	HIT91
DT225TCL	93-90	164.3ci - 225HP	31100-87D10	HIT91
DT225TCL EFI	00-94	164.3ci - 225HP	31100-87D10	HIT91
DT225TCX	93-90	164.3ci - 225HP	31100-87D10	HIT91
DT225TCX EFI	03-01	164.3ci - 225HP	31100-92E00	HIT91
DT225TCX EFI	00-94	164.3ci - 225HP	31100-87D10	HIT91
DT225TCXG	93	164.3ci - 225HP	31100-87D10	HIT91
DT225TCXG EFI	00-94	164.3ci - 225HP	31100-87D10	HIT91
PU140 EFI Jet	97	108.2ci - 100HP	31100-87D10	HIT91



